Title:	Error 4000h	ID:
		0097

Date in:	Response:	Model:	Author:
2004-10-01	*2004-10-01*	-	*CMa*

Q:

Just got an error, where we timed out waiting for the ready bit.
The code was 16384. What does that mean to you?

A:

You activated the BCR mode by sending an ST 1910