Title:	Installation of Transfer Station		ID:
			0050
Date in:	**Response:**	**Model:**	**Author:**
2007-07-19	*2007-07-19*	*-*	

How to mount a X-Fer Station

Applicable for all Liconic Units
except: STR-Series and STX40

1. Mounting Kit not yet attached





Mounting-Kit

Do not tighten the screws. leaf them a little lose, so you are able to move the Mounting-Kit

Positioning bolts:
As soon as the Mounting-Kit is adjusted, you are able to remove and reattach the Transferstation and the position always remains the same.

Thread for Taransferstation fixation



Mount the Transferstation. Do not tighten the screw, should be able to move the Transferstation



To extend the shovel the use of the STXFer-Program is recommended. For the use of the program see the STXFer document.





2. Mounting Kit already attached (changing Transferstation)




Positioning bolts place the Transferstation in the same Position
Remove Transferstation
Mount new Transferstation and tighten this screw.
Check the adjustment