

Title:	Fuse blow on cooled StoreX			ID:
				0110
Date in:	Response:	Model:	Author:	
2003-06-18	2003-06-18	-	CMa	

Q:

We keep on blowing the fuses in the Storexes. What rating and size should we use? I remember last year you sent us some, but we have run out. Could you let us know, so we can see if we can order some here?

A:

8A slow. You should avoid turning the units on and off. After turning a unit off you should allow the pressure in the compressor to reduce ~10..15 min.