

Title:	Alarm Sound on STXFER 32			ID:
				0006
Date in:	Response:	Model:	Author:	
2006-05-08	2006-05-08	STX220	C <i>Ma</i>	

Q:

STX220 alarm sounds, when STXFER32 software is finished by ESC key. It doesn't stop even though unit's initialize button is pushed. Initialize by "ST 1900, ST 1801" only can stop it.

A:

While you're in this program the service mode is activated. The alarm sounds because the Gate is open. You have to close it ("ST 1902")