

Title:	Beeping Error after Access	ID:	
		<i>0017</i>	
Date in:	Response:	Model:	Author:
<i>2003-06-13</i>	<i>2003-06-13</i>	<i>STX40</i>	<i>CMa</i>

Q:

We have some trouble with a Storex 40.
It gives a "beep" error every time it opens the handler door!
Do you have any hints, suggestions?

A:

Check if the glass door knob activates the sensor.