

Title:	Solenoid Chattering	ID:	
			0276
Date in:	Response:	Model:	Author:
2007-05-01	2007-05-01	STX40	CMa

Q:

On my STX40-HRBT I occasionally hear solenoid chattering

A:

A common cause is low mains voltage. The switching performance may be improved by adding an O-ring according following procedure

