

<b>Title:</b>	<b>Deep Freezer Running at Plus Temperatures</b>	<b>ID:</b>	
		0330	
<b>Date in:</b>	<b>Response:</b>	<b>Model:</b>	<b>Author:</b>
2008-10-21	2008-10-21	STX1000	CMa

**Q:**

This STX 1000 is currently running at -20C, we need this at +18C, I know you mentioned before we need to adjust the expansion valve, please send procedure ASAP so we can get our refrigeration guy to adjust this.

**A:**

No need for adjustment but check if there is no back-freezing at the compressor suction