

LED	Perm.	Blink. Slow	Blink Fast	Blinking Interm.	
red	NoHV	GenError	WarningRest		
orange	1stON	1stEnabled	1stOverTemp	1stOverPress	
green	2ndON	2ndEnabled	2ndOverTemp	2ndOverPress	Stepper Valve Moving