


Title:	STR240 Tilted Lift Column			ID:
				134
04.07.14	Response:	Model:	Author:	
		-	CMa	

STR240 Tilted Lift Column




Periscop Plate was right mounted?

Roller bearings must be in angle. If not, the Bearing Bolt is damaged

Remove the middle screw with the bearing

ATTENTION mount the bearing in the same direction as it been removed!



Check these 3 screws if tight, if not tighten and secure with Loctite.