




Title:	Sealing of Stepper Motor Connector	ID:	
		0093	
Date in:	Response:	Model:	Author:
2010-02-10	2010-02-10		RKi

Sealing of stepper motor connector







Picture 1: View of connector without any silicone



Picture 2: Apply silicone in the are of connectors



Picture 3: Fill silicone into cover cap



Picture 4: Applying cap

Flatten the silicone and remove the surplus silicone. This is best done with a wetted finger.



Picture 5: Finished connector sealing